
maintaining the data needed, and c including suggestions for reducing	lection of information is estimated to ompleting and reviewing the collect this burden, to Washington Headqu uld be aware that notwithstanding an DMB control number.	ion of information. Send comments arters Services, Directorate for Info	regarding this burden estimate ormation Operations and Reports	or any other aspect of the 1215 Jefferson Davis	nis collection of information, Highway, Suite 1204, Arlington
1. REPORT DATE 2.		2. REPORT TYPE	3. DATES COVERED 00-00-1981 to 00-00-1981		
4. TITLE AND SUBTITLE		5a. CONTRACT NUMBER			
Biological Effects of Beach Restoration on the Florida Gulf Coast				5b. GRANT NUMBER	
				5c. PROGRAM ELEMENT NUMBER	
6. AUTHOR(S)				5d. PROJECT NUMBER	
				5e. TASK NUMBER	
				5f. WORK UNIT NUMBER	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Army Corps of Engineers (USACE), Coastal and Hydraulics Laboratory, 3909 Halls Ferry Road, Vicksburg, MS, 39180				8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)	
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)	
12. DISTRIBUTION/AVAIL Approved for publ	ABILITY STATEMENT ic release; distributi	on unlimited			
13. SUPPLEMENTARY NO	OTES				
14. ABSTRACT					
15. SUBJECT TERMS					
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified	Same as Report (SAR)	2	

Report Documentation Page

Form Approved OMB No. 0704-0188




Coastal Engineering Technical Note

BIOLOGICAL EFFECTS OF BEACH RESTORATION ON THE FLORIDA GULF COAST

PROBLEM: Beach restoration with dredged material can provide a means of counteracting beach erosion in some coastal areas. Therefore, the Corps is presently using this method to solve coastal erosion problems. As an Environmental Impact Statement is required for these projects, the Corps is having to answer many environmental questions about the effects of beach restoration. At present, available information is needed to substantiate the required evaluations. Studies at Panama City Beach, Florida (Culter and Mahadevan, 1981 and Saloman, Naughton and Taylor, 1981) and Treasure Island, Florida (Saloman, 1974 and Taylor Biological Company, 1978) provide guidance for the planning of beach restoration projects along the Florida gulf coast and evaluating its potential biological impact (see Location Map).

EFFECTS OF BEACH RESTORATION: As in other coastal regions, there are varying wave energy conditions along the gulf coast. Panama City Beach is in a moderately high wave energy area, whereas Treasure Island is in a moderately low wave energy area. The macrobenthic communities in the nearshore area at the two projects were rich and diverse, except in the swash zone. As a result of wave energy, the nearshore sediments experienced am almost constant agita-This agitation dictated the type of macrobenthic animals inhabiting the nearshore area. Most macrobenthic animals were active burrowers or crawlers capable of quickly digging into the sediments if threatened with displacement. It was found that the beach restoration projects in both coastal environments did not result in any discernable, long-term effects on the nearshore macrobenthic animals. In these and other coastal areas, studies have shown



Site Location Map

that the nearshore communities are resilient and show no lasting effects resulting from beach restoration projects. See CETN-V-5 and CETN-V-7 for results of studies on the Atlantic and Pacific Coasts, respectively.

However, major differences were found in the recovery rate of the offshore borrow pits in the two geographic areas. At Treasure Island, it was found that the offshore borrow pit sediments contained a high percentage of organic matter and hydrogen sulfide and the water was occasionally low in dissolved oxygen. This resulted in a generally poor quality of habitat; thus, the abundance and diversity of macrobenthic fauna in the pits were lower than the undisturbed substra-

tum in adjacent areas. It was found that the pits are in a slow state of recovery and it may take 10 years or more for them to completely recover.

In contrast, the offshore borrow pits dredged in 1976 at Panama City Beach rapidly filled with sediment from adjacent areas and did not act as a trap for fine particles and organic matter as observed at Treasure Island. Dredging did cause an immediate decline in the bottom communities, but it was followed by a rapid recovery that was virtually complete in about one year. The borrow pits had no discernable long-term effects on the macrobenthic animals. The recovery rates of the two borrow areas were thought to be related to the differing physical environments in the two geographical regions and the resiliency of the macrobenthic animals.

CONCLUSIONS: Macrobenthic animal recovery apparently is rapid following beach restoration, but it may take 10 years or more for some borrow areas to recover, depending on the physical and chemical conditions, i.e., currents, sediment movements, and water quality. To improve macrobenthic animal recovery rates, consideration should be given to shallow dredging over large low wave energy areas rather than deep dredging. Although biological damage would be initially greater, recovery would be expected to be much quicker in the shallow dredged area.

ADDITIONAL INFORMATION: Contact the CERC Coastal Ecology Branch at (202) 325-7393.

REFERENCES:

- CULTER, J. K., and MAHADEVAN, S., "A Study of Benthic Fauna of Sandy Beaches and Nearshore Areas of Panama City, Florida, "Draft Technical Report prepared for CERC by Mote Marine Laboratory, Sarasota, FL, July 1981.
- SALOMAN, C. H., "Physical, Chemical and Biological Characteristics of Near-shore Zone of Sandy Key, Florida, Prior to Beach Restoration," Final Report for the Coastal Engineering Research Center, National Marine Fisheries Service, Panama City, FL, 1974.
- SALOMAN, C. H., NAUGHTON, S. P. and TAYLOR, J. L., "Short-Term Effects of Beach Nourishment on Benthic Fauna of Borrow Pits and Adjacent Sediment, Panama City, FL," Draft Technical Report prepared for CERC by Taylor Biological Company, Inc., Lynn Haven, FL, Sep.1981.
- TAY LOR BIOLOGICAL COMPANY, "Ecological Comparison of Beaches, Offshore Borrow Sites and Adjacent Bottom at Anna Maria Island and Treasure Island, Florida," prepared for the US Army Corps of Engineers, Jacksonville District, DACW 17-78-M-1410, Dec.1978, 35 p.
- U.S. ARMY CORPS OF ENGINEERS, COASTAL ENGINEERING RESEARCH CENTER, "Biological Effects of Beach Restoration Projects on the South Atlantic U.S. Coast," CETN-V-5, Fort Belvoir, VA, 1980.
- U.S. ARMY CORPS OF ENGINEERS, COASTAL ENGINEERING RESEARCH CENTER, "Biological Effects of Beach Restoration on the Southern California Coast," CETN-V-7, Fort Belvoir, VA, 1981.